



# PRICE LIST

2024

“labour, sundries and consumables  
only”

**Banking Details:**

Standard Bank, Port Elizabeth

Account type: Current

Account no: 10125483145

Branch code: 051 001

**Address: 04 Muller Street**

**Bothasrus**

**Despatch**

**Cell: 082 592 8040**

**Email: [lalliesevents@gmail.com](mailto:lalliesevents@gmail.com)**



Address: 04 Muller Street  
 Bothasrus  
 Despatch  
 Cell: 082 592 8040  
 Email: lalliesevents@gmail.com

## Price List, Lallies Guitar/Amplification Repairs 2024

**Acoustic Guitar (Includes Classical, figure of 8, dreadnought/Excludes Hollow body),** prices exclude parts whether supplied by the client or otherwise

<i>Re-String (IF STRINGS NOT PURCHASED AT LALLIES)</i> .....	R50
<i>Route out bridge to lower action</i> .....	R250
<b>Full Set up</b> (ACTION ADJUSTMENT,SADDLE SEATING, INTONATION SETTING, NUT SLOTTING, LEVELLING AND CROWNING/ POLISHING ALL FRETS, CLEANING TARNISHED HARDWARE, POLISHING BODY, OILING FRETBOARD).....	R1300
<b>Partial Set up</b> (ACTION ADJUSTMENT,SADDLE SEATING, INTONATION SETTING, NUT SLOTTING, LEVELLING AND CROWNING/ POLISHING ONLY HIGH FRETS, CLEANING TARNISHED HARDWARE, POLISHING BODY, OILING FRETBOARD).....	R850
<b>Major Set up</b> (POLISH, FLAT, BUFF, FULL SET UP, REPLACE ALL SCREWS).....	R2000
<i>Replacement of nut/saddle (INCLUDING SLOTTING)</i> .....	R250
<i>Chip in paint/ Deep Scratch (ONLY GLOSS COATS)</i> .....	R600
<i>Fitting of pickup</i> .....	R550
<i>Re-fret</i> .....	R1800
<i>Crowning / Levelling of Frets</i> .....	R800
<i>Loose Fret/File Fret Ends</i> .....	R250
<i>Polish and Buff</i> .....	R850
<i>Machine head replacement (1)</i> .....	R300
<i>Machine heads Replacement (6)</i> .....	R600
<i>Hole in body</i> .....	POQ
<i>Neck replacement</i> .....	POQ
<i>Laminating coming loose</i> .....	POQ
<i>Full Restoration</i> .....	POQ
<i>Broken Headstock/Crack in body or Neck</i> .....	R5500
<i>Bridge re-attach</i> .....	R1400
<i>Fret board loose</i> .....	R2900
<i>Binding Repair</i> .....	R950
<i>Pick guard replacement</i> .....	R250
<i>Re-spray (ONLY SOLID WOOD ACOUSTICS—TOP, BACK AND SIDES)</i> .....	R6000
<i>Truss Rod replacement/Repair</i> .....	R4800
<i>Mould build up</i> .....	R350
<i>Electronics fault</i> .....	POQ
<i>Jack repair/replacement</i> .....	R250
<i>Decal Replacement</i> .....	R650
<i>Strap pins (INCLUDING STRAP PIN)</i> .....	R250
<i>Fretboard Inlay Replacements (NOT APPLICABLE TO DOT INLAYS)</i> .....	R2500



Address: 04 Muller Street  
Bothasrus  
Despatch  
Cell: 082 592 8040  
Email: lalliesevents@gmail.com

## Price List, Lallies Guitar/Amplification Repairs 2024

**Electric Guitar (Includes Hollow body, Excludes MIDI enabled guitars),** prices exclude parts whether supplied by the client or otherwise

<i>Re-String (IF STRINGS NOT PURCHASED AT LALLIES)</i> .....	R50
<b>Full Set up</b> (ACTION ADJUSTMENT,SADDLE HEIGHT, INTONATION SETTING, NUT SLOTTING, LEVELLING AND CROWNING/ POLISHING ALL FRETS, CLEANING TARNISHED HARDWARE, POLISHING BODY, OILING FRETBOARD, PICKUP HEIGHT).....	R1300
<b>Partial Set up</b> (ACTION ADJUSTMENT,SADDLE HEIGHT, INTONATION SETTING, NUT SLOTTING, LEVELLING AND CROWNING/ POLISHING ONLY HIGH FRETS,CLEANING TARNISHED HARDWARE,POLISHING BODY,OILING FRETBOARD,PICKUP HEIGHT)..	R850
<b>Major Set up</b> (POLISH, FLAT, BUFF, FULL SET UP, REPLACE ALL SCREWS).....	R2000
Replacement of nut/saddle (INCLUDING SLOTTING).....	R250
Chip in paint/ Deep Scratch (ONLY GLOSS COATS).....	R600
Re-fret (NOT INCLUDING MAPLE FRETBOARDS).....	R1800
Re-fret of Maple Fretboard.....	R3200
Crowning / Levelling of Frets.....	R800
Polish and Buff.....	R850
Machine head replacement (1).....	R300
Machine heads Replacement (6).....	R600
Broken Headstock/Crack in body or Neck.....	R5500
Hole in body (Hollow body).....	POQ
Damaged neck to body joint.....	POQ
Neck replacement.....	POQ
Laminating coming loose (Hollow body).....	POQ
Full Restoration.....	POQ
Bridge replacement and Seating / Intonating (Hollow body).....	R1450
Fret board loose.....	R2800
Binding Repair.....	R650
Pick guard replacement.....	R450
Re-spray.....	R5500
Truss Rod replacement/Repair.....	R4800
Mould build up (Hollow body).....	R350
Decal Replacement.....	R650
Jack repair/replacement.....	R250
Fitting Treble Bleed (Including Part).....	R200 per pot
Fitting alternative tone capacitor (Including Part).....	R200 per pot
Replacing a pot/s.....	R200
Strap pins (INCLUDING STRAP PIN).....	R250



Address: 04 Muller Street  
Bothasrus  
Despatch  
Cell: 082 592 8040  
Email: lalliesevents@gmail.com

## Price List, Lallies Guitar/Amplification Repairs 2024

### Electric Guitar (Continuing from previous page)

Re-wire Electronics.....	R500
<b>Re-wire/Repair Single Coil Pickup.....</b>	<b>R3000</b>
<b>Re-wire/Repair Humbucker Pickup.....</b>	<b>R4500</b>
Replace Pickup surround.....	R250
Replace Pickup springs/Silicon.....	R150
Modify wiring.....	R450
Replace Selector.....	R250
Replace Pickups.....	R550
Fitting Floyd Rose Setup.....	POA
Gold Plating hardware.....	POA
Replace/fit Machine head trees.....	R250
Modifying to String through body.....	R1800
Modifying to Tremolo Style bridge (Floyd Rose).....	R4600
Replacing all Screws.....	R450
Cleaning all Screws.....	R150
Replacing of any hardware components (without modification).....	R250
Install Tone Split pod.....	R450

**Miscellaneous**, the following does not include the price of any components required to manufacture/build.

Special cable construction.....	R350
Modification of Existing Cable.....	R150
Pre-wired Les Paul Harness.....	R1150
Prewired Stratocaster Harness.....	R800
Pre-wired Telecaster Harness.....	R800
Pre-wired Jimmy Page Harness.....	R1500
Pre-wired Steve Vai Harness.....	R1200
Pre-wired Superstrat Harness.....	R1000
Pre-wired Bass guitar Harness.....	R680
Pre-wired Acoustic Guitar Harness.....	R900
Special Pedal build.....	POQ



Address: 04 Muller Street  
 Bothasrus  
 Despatch  
 Cell: 082 592 8040  
 Email: lalliesevents@gmail.com

**Price List, Lallies Guitar/Amplification Repairs 2024**

**Amplification Repairs (Includes Combo Amplifiers, Stack and Cab Amplifiers, Individual Pedals)** prices quoted exclude parts.

<i>Speaker Cone Repair</i> .....	R850
<b><i>Speaker Re-coil (8 and 10 inch)</i></b> .....	<b>R650</b>
<b><i>Speaker Re-coil (12 and 15 inch)</i></b> .....	<b>R750</b>
<b><i>Speaker Re-coil (18 inch and larger)</i></b> .....	<b>R850</b>
<i>Replace Power Supply</i> .....	POQ
<i>Replace kettle plug (female)</i> .....	R200
<i>Blown Fuse</i> .....	R150
<i>Transformer Replacement</i> .....	POQ
<i>Speaker Replacement (LABOR FOR FITMENT ALONE)</i> .....	R300
<i>Re-covering of amplifier casing</i> .....	R1800
<i>Building of new amplifier casing</i> .....	R4500
<i>Replacing damaged Pot</i> .....	R350
<i>Replacing Cooling fan</i> .....	R650
<i>Fault Finding/Quoting</i> .....	R400
<i>Replacing handles/corners/feet</i> .....	R250
<i>Custom kettle cord</i> .....	R250
<i>Replace ON/OFF push buttons/switches</i> .....	R300
<i>Full Restoration</i> .....	POQ
<b><i>Minor Service (SPRAY,ASSESS SPEAKERS,SKREWS,WIRING,MINOR REPAIRS)</i></b> .....	<b>R1250</b>
<b><i>Major Service (SPRAY,ASSESS SPEAKERS,SKREWS,WIRING,TRACK REPAIRS,MINOR REPAIRS)</i></b> .....	<b>R1650</b>
<i>Netting Replacement</i> .....	R1800
<i>Replace Valve</i> .....	POQ
<i>Service Valve Amplifier/Head</i> .....	POQ
<i>Replace Knob (part supplied)</i> .....	R120 per pod
<i>Customisation of amplifier</i> .....	POQ
<i>Re-wire Amplifier</i> .....	POQ
<i>Lining amplifier with damping material (part supplied)</i> .....	R450
<i>Fitting Line out</i> .....	POQ
<i>Replace L.E.D (part supplied)</i> .....	R250
<i>Electronic Instrument Repairs</i> .....	POQ



Address: 04 Muller Street  
 Bothasrus  
 Despatch  
 Cell: 082 592 8040  
 Email: lalliesevents@gmail.com

**Price List, Lallies Guitar/Amplification Repairs 2024**

**Amplification Repairs**

**Includes:** PA systems, Passive and Active Mixers and Speakers, Guitar Amplifiers, Keyboard Amplifiers, Loose cables and Speaker Crossovers.

**Excludes:** Power amplifiers, surface mount component equipment, Home Theatre Equipment/Car audio and Record Players/other media players.

*All repairs carry a R400 quotation charge if the quotation is unaccepted/unpaid and these repairs take roughly take ±2 weeks to complete (See Terms and Conditions attached for Repair Process)*

**Metal Structures (Stands, pedal casings)** due to constant price changes the following cannot be fixed, yet rather listed as a to display what repairs we can carry out on such items.

Re-Chroming.....	POQ
Powder Coating.....	POQ
Re-Spray.....	POQ
Rust Removal.....	POQ
Plastic component repairs/replacements.....	POQ
Metal component repairs/replacement.....	POQ
Foam Replacement.....	POQ
Rubber feet Replacement.....	POQ
Building of custom stand.....	POQ
Building of custom pedal board.....	POQ

**Call Out Fee's**, the following includes minor repairs assessed on site or setting requirements for PA systems, stage restructuring and/or fault finding.

Uitenhage.....	R250
Despatch.....	R150
Port Elizabeth.....	R450